CORNER RECORD

	Document Number 20160016
City of N/A	County of Placer , California
Brief Legal Description Lot 2 of L MAPS 56	
CORNER TYPE	COORDINATES(Optional)
S34 T.11N. R.7E. Meander Rancho Control Property Control Other	N
Date of Survey 6-7-16	Vert. Datum: NGVD29 NADV88 Meas. Units: Metric Imperial
Corner - Left as found Found and tagged	Established Reestablished Kebuilt
Identification and type of corner found: Evidence used to identify or proposed railroad spike stamped "LS 3636" and 3/4" iron pins at lot corners. Use Basis of Bearings, to re-establish so	sed said map & monuments found for
A description of the physical condition of the monument as found and as set or reset: Found Southeast corner to be destroyed by driveway pedistal. Set 3/4" iron pipe with plug stamped PLS 8278" at 1.00 foot R.P. radial southwest of original corner COCCOCCOCCOCCOCCOCCOCCOCCOCCOCCOCCOCCOC	
SURVEYOR'S STATEMENT	RDS RDS
This Corner Record was prepared by me or under my direction	in conformance with 2016 PLS 8278 PLS 8278
This Corner Record was received,	and examined
and filed October 19, 2016 Signed She Husberry P.L.S. or Rec.E. N Title Country Surveyor's Comment	AMON

OF CORNER RECORDS, PAGE